

Keithley Instruments, Inc.  
28775 Aurora Road  
Cleveland, Ohio 44139  
1-888-KEITHLEY  
www.keithley.com

## Firmware Revision Installation Instructions

### To install updated firmware for the Model 2100:

**NOTE** You must have one of the following items installed on your computer in order to obtain the proper VISA layer (Keithley Instruments I/O Layer 5.0 is included on the CD-ROM that came with your Model 2100):

- NI-VISA 3.1 or greater

1. Connect your Model 2100 to your computer with the included USB cable.
2. Insert the Product Information CD-ROM that came with your Model 2100 into the CD drive of your computer (or navigate to the files you downloaded from the Keithley Instruments website) and double-click the **DmmUpdate.exe** file to begin the installation of the Model 2100 firmware update.
3. When the 2100 (USBTMC) Update Version window appears, click the **Select** button (see Figure 1-1).


Figure 1-1  
Installing the Model 2100 firmware update



4. The Open dialog box will appear. The files for the front-end firmware and the digital signal processor (DSP) updates are listed (see Figure 1-2):
  - 1232\_xxx.bin Updates the front-end firmware version
  - 5407\_xx.xx.bin Updates the DSP firmware version


**NOTE** Filenames may vary, depending upon which version of firmware you are installing. The "xx.xx" and "xxx" in the filenames in this example represent alpha-numeric values that denote specific firmware revisions.

Figure 1-2  
**The Open dialog box**



5. Highlight the **5407\_xx.xx.bin** file and click **Open** (see Figure 1-2) to start the DSP firmware version update. The 2100 (USBTMC) Update Version window will display a "Please wait" message while the file is executing, as shown in Figure 1-3.

Figure 1-3  
**Model 2100 firmware upgrade in progress**



6. Once installation of the DSP firmware update file is complete, you will be prompted to restart your Model 2100 to continue the update (see Figure 1-4). Power the Model 2100 off, and then power it on again.

Figure 1-4  
Restart the Model 2100



**NOTE** An error message may appear on the front-panel display when you restart your Model 2100. If it does, you will need to click **Continue** and install the front-end firmware revision update file (1232\_###.bin) following the procedures listed above.

*If you do not receive an error message, you do not need to install the 1232\_###.bin update file.*

7. The 2100 (USBTMC) Update Version window will reappear when the installation is complete. Click **Exit** to exit the firmware update installation (see Figure 1-4).

To confirm the update has been properly completed, check the firmware revision:

1. Press the **MENU** key and then use the **PREV** and **NEXT** keys to select the **SYSTEM** submenu.
2. Press **ENTER**, then use the **PREV** and **NEXT** keys to select the **SYSTEM VER.** option.
3. Press **ENTER** to select it; a three-part code in xx-xx-xx format will appear on the display. The first part of the code, xx.xx, is the firmware version of the digital signal processor (DSP); the second code, xx, represents the panel microprocessor; and the last code, xx, indicates the front-end processor firmware version.